H-NWT Nut Work Table
H-NWT-600D Replacemet Diamond Sheets for H-NWT

This Nut and Saddle shaping tool has 3 different tables with #600 grit diamond.
Flat table and 90 degree angles are precisely processed by CNC machine.



1) 35mm x 180mm flat table
   Use for flat surface job
2) 4mm x 180mm 90 degree corner table
   Use for 90 degree sanding of saddles
3) 10mm x 180mm 90 degree corner table
   Use for 90 degree sanding of nuts

Nut shaping:
Please make flat bottom by using 1).
And then make 90 degree angle perfectly by using 3).

Saddle shaping:
First of all, please make one side of saddle flat by using 1).
Then sand another side to make flat and adjust the thickness.
Lastly make 90 degree angled bottom by using 2).
2) diamond face is 30 degree angled to sand the saddle ergonomically.

Replacement diamond sheets are available.
If the diamond powders are gone, please replace the diamond sheets to the new ones.